



說明: B工區-106.10.16 既有箱涵通水斷面不足, 易遭受土砂雜木堵塞, 形成易致災區段